

## 1 Purpose

This document describes the fixed bugs and problems as well as improvements in the following new firmware version:

- 5.893.0014

in comparison with the firmware version:

- 5.893.0012

The instruments 892, 893 and 895 have the identical firmware but are configured differently.



### CAUTION

#### Condition

The previous version, **5.893.0012**, must be installed on the instrument in order for the new firmware to be installed.

## 2 Improvements

- The temperature measurement and its adjustment have been improved.
- The stability of the gas flow control has been improved.

## 3 Fixed bugs and problems

- Support of a new electronic circuit in the instrument.

## 4 Known errors

- none

Herisau, June 23, 2014

---



P. Hunziker  
Vice President,  
Head of Development



U. Kürsteiner  
Head of Quality Management