

1 Purpose

This document describes the fixed bugs and problems as well as improvements in the following new firmware version:

- 5.893.0015

in comparison with the firmware version:

- 5.893.0014

The instruments 892, 893 and 895 have the identical firmware but are configured differently.



NOTE

Prerequisite

The version **5.893.0012** must be installed on the instrument in order for the new firmware to be installed.

2 Changes

- The firmware had to be adjusted due to the installation of a new storage module (hardware change).
The new 5.893.0015 firmware is compatible with all instrument versions.

3 Fixed bugs and problems

- none

4 Known bugs

- none

Herisau, May 12, 2017



P. Hunziker
Vice President,
Head of Development



M. Saba
Head of Quality Management