

Metrohm AG CH-9100 Herisau Switzerland Phone +41 71 353 85 85 Fax +41 71 353 89 01 info@metrohm.com www.metrohm.com

892 Professional Rancimat 893 Professional Biodiesel Rancimat 895 Professional PVC Thermomat

Release Notes

1 Purpose

This document describes the fixed bugs and problems as well as improvements in the following new firmware version:

5.893.0017

in comparison with the firmware version:

5.893.0014

The instruments 892, 893 and 895 have the identical firmware but are configured differently.



NOTICE

Prerequisite

The version **5.893.0012** must be installed on the instrument in order for the new firmware to be installed.

2 Changes

• The firmware had to be adjusted due to the installation of a new storage module (hardware change).

The new 5.893.0017 firmware is compatible with all instrument versions.

3 Fixed bugs and problems

none

4 Known bugs

none

8.893.8006EN **1**

5 Improvements

• improved adjustment

Herisau, June 6, 2018

P. Hunziker

Vice President, Head of Development M. Saba

Dr. U. Loka

Head of Quality Management & Regulatory Affairs