

Metrohm AG CH-9100 Herisau Switzerland Phone +41 71 353 85 85 Fax +41 71 353 89 01 info@metrohm.com www.metrohm.com

892 Professional Rancimat 893 Professional Biodiesel Rancimat 895 Professional PVC Thermomat

Release Notes

1 Purpose

This document describes the fixed bugs and problems as well as improvements in the following new firmware version:

5.893.0012

in comparison with the firmware version:

5.893.0011

The instruments 892, 893 and 895 have the identical firmware but are configured differently.

2 Improvements

Long-term stability in continuous operation has been improved.
(No changes in the firmware that can be accessed by the customer)

3 Fixed bugs and problems

- Instrument crashes due to an application error have been eliminated (error message: "Application error J9W.exe").
- The instrument does no longer freeze and generate an empty error message when used for several days.
- The quality and stability issues in the operating system have been resolved.
- Communication with the test laboratory software has been improved.

4 Known errors

none

8.893.8002EN **1**

Herisau, October 29, 2013

P. Hunziker

Vice President, Head of Development N. Mnt

U. Kürsteiner

Head of Quality Management